

Storm Damage Report (updated on 13.06.2022 till 9:00 P.M.)

Date of occurrence	District	Rev. Circle	Name of Village affected	No. of Village affected	Total Population affected	Houses Damaged					Human life lost	Crop Damage (In Hect)	Other loss (Livestock, Road Communication etc)	Ex-Gratia distributed	GPS Co-ordinates	Remarks
						Partially Damaged		Fully damaged		Any other Institutions affected						
						Kutcha	Pucca	Kutcha	Pucca							
11-06-2022	Dhubri	Golokganj	<u>Golokganj R.C.</u> - Ramnathpara	1	5	0	0	1	0	0	0	0	Cash, Gold, Silver, Rice, Furniture, Utensil, Mattress, Mobile Phone, Fan & Other important document.	-	-	As per report submitted by the Circle Officer, during the lightning incident on the night of 11-06-2022. One (01) no. Of Kutcha house was fully damaged. The name of house owner is Habijul Islam, S/O- Lt. Hanifuddin Sk.
11-06-2022	Charang	Bengtol	<u>Bengtol R.C.</u> - Patabari FV (Langkhar Nao Ghat at village Dangabari FV)	1	0	0	0	0	0	0	0	0	-	-	26.73145, 90.524497	At around 60:40 pm a lightning incident took place due to which a person namely shri Gelsing Muchahary sustained serve injuries . At present the victim is being treated at Crofts Memorial Hospital, Tukrajhar.
11.06.2022	Kokrajhar	Kokrajhar	<u>Kokrajhar R.C.</u> - Bhog Amguri (West Mainaguri)	1	0	0	0	0	0	0	0	0	2 Cows & 1 Bull	-	-	-
12-06-2022	Lakhimpur	Nowboicha, Kadam	<u>Nowboicha R.C.</u> - Borgoya Khagori, Dolohal, 12 Mail , Ahomoni, Deja, Dorongrya, Phukan Doloni, Khanjan, Rowdoring Borpathar, Phulbari, Gandhali, Borgoya Muri, ,Dhekiajuli, Ahom Gaon, Bharuluwa <u>Kadam R.C.</u> - Gohain NC	16	0	0	0	0	0	0	0	0	-	-	27.308045, 94.170756	APDCL PSC Pole 7.5= 07nos PSC Pole 8.5= 06 nos Conductor 8.5 & 1.5 km (under Nowboicha & Boginadi Electricity Sub-Div)
12-06-2022	Goalpara	Lakhimpur, Ranjuli	-	0	0	0	0	0	0	0	0	0	-	-	-	<u>APDCL Lakhimpur ESD</u> Nos. of LT Pole Damage: 18 Nos LT Conductor Snaping 4.9 K.M and DTR - 1 Nos. (25KVA) <u>APDCL Dhupdhara ESD</u> 1. 25 KVA Transformer damaged at Shyamagaon Pt. I, 2.63 KVA Transformer damaged at Dhanbori Nos. of HT Poles Damaged : 5 Nos.
12-06-2022	Dhubri	Dhubri, Bilasipara, Agomani	<u>Dhubri R.C.</u> - Kuntirchar Pt-I Adabari Pt- II Jhagraper Pt- III Jhagraper Pt-I Chagolchora Pt-I Falimari Pt-II Airanjangla Pt-I, <u>Bilasipara R.C.</u> - Udmari Pt-I Hatipota Pt-II, <u>Agomani R.C.</u> - Bishkhowa Pt-I, Bishkhowa Pt-II, Pachim Kanuri Pt-I, Pachim Kanuri Pt-II, bidyardabri Pt-iv	14	213	0	0	0	0	0	0	0	-	-	-	1.PSC Poles – 9 2.Conductor-6.5 KM 3. Transformer-3, Electrical Sub Division of Bilasipara damage 8.5 mtr – 2, Electrical sub div of Agomani damage PSC pole (no) 7.5 mtr-1 Nos 8.5 mtr-5 Nos 9.75 mtr-4 Nos Damaged conductor (KM) HT-3 & amp; LT- 2, consumer affected (approx)-7000
Total				33	218	0	0	1	0	0	0	0	-	-	-	-