

**Storm Damage Report (updated on 26.07.2022 till 10:00 P.M.)**

Date of occurrence	District	Rev. Circle	Name of Village affected	No. of Village affected	Total Population affected	Houses Damaged				Any other Institutions affected	Human life lost	Crop Damage ( In Hect)	Other loss (Livestock, Road Communication etc)	Ex-Gratia distributed	Time	GPS Co-ordinates	Remarks
						Partially Damaged		Fully damaged									
						Kutcha	Pucca	Kutcha	Pucca								
25.07.2022	Dibrugarh	Moran	<u>Moran R.C.</u> :Tenga koch, Nakhat,Bamun bari, Tiloi jan, Phatikachowa, Phatikachowa ahom gaon, Tiloi, Khowang Sonowal bongali, Madhakali, Demokinar changmai gaon	10	0	0	0	0	0	0	0	Name of the division:_ Dibrugarh Electrical Sub Division) Distribution Transformer 1 PSC Pole 8.5 M 11 ACRS Rabbit in KM 2.95 GI LT Angle Cross Arm 9 Pole clamp of GI flat (50x6) 6 LT pin Insulator 9 Shackle Insulator 7	0	0	0	-	
25.07.2022	Dibrugarh	Dibrugarh west	<u>Dibrugarh west R.C.</u> :Lezai, Bordoibam	2	0	0	0	0	0	0	0	Name of the division:_ Dibrugarh Electrical Sub Division) PSC Pole 8.5 M 1 ACRS Rabbit in KM 0.05 GI Channel 1 LT pin Insulator 2	0	0	0	-	
25.07.2022	Lakhimpur	Subansiri	<u>Subansiri R.C.</u> :No 2 parghat	1	0	0	0	0	0	0	0	Bull-1 no <u>Details of cow Owner-</u> Tularam Gohain vill- No 2 parghat P.O- Ghilamara Dist- Lakhimpur	0	0	27.2770 2 N 94.4251 2 E	-	
<b>Total</b>				<b>13</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	-	-	-	-	-	